EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	73820	(increase increasing) near4 load	US-PGPUB; USPAT	OR	ON	2007/03/08 10:18
L2	1938	"318"/685,696.ccls.	US-PGPUB; USPAT	OR	ON	2007/03/08 10:18
L3	1938	L2	US-PGPUB; USPAT	OR	ON	2007/03/08 10:18
L4	23189	(zero-cross\$3) or (zero adj cross\$3)	US-PGPUB; USPAT	OR	ON	2007/03/08 10:18
L5	23189	L4	US-PGPUB; USPAT	OR	ON	2007/03/08 10:18
L6	59	L3 and L5	US-PGPUB; USPAT	OR	ON	2007/03/08 10:18
L7	171513	(measure measuring sensing sensor detector detecting detection detect) near3 current	US-PGPUB; USPAT	OR	ON ·	2007/03/08 14:03
L8	20	L6 and L7	US-PGPUB; USPAT	OR	ON	2007/03/08 10:18
L9	20	L8	US-PGPUB; USPAT	OR	ON	2007/03/08 10:18
L10	5	1 and 9	US-PGPUB; USPAT	OR	ON	2007/03/08 10:56
L11	13	1 and 6	US-PGPUB; USPAT	OR	ON	2007/03/08 11:00
L12	75884	reference near2 position	US-PGPUB; USPAT	OR	ON	2007/03/08 14:02
L13	16850	(step stepper) near2 (motor actuator)	US-PGPUB	OR	ON	2007/03/08 14:03
L14	872719	mode or state	US-PGPUB	OR	ON	2007/03/08 14:03
L15	55186	(measure measuring sensing sensor detector detecting detection detect) near3 current	US-PGPUB	OR	ON	2007/03/08 14:03
L16	202	12 and 13 and 14 and 15	US-PGPUB	OR	ON	2007/03/08 14:04
L17	5316	(zero-cross\$3) or (zero adj cross\$3)	US-PGPUB	OR	ON	2007/03/08 14:05
L18	9	16 and 17	US-PGPUB	OR	ON	2007/03/08 14:05
L19	7579	(mechanic mechanical physically) with (stop stopping stoppage)	UŞ-PGPUB	OR	ON	2007/03/08 14:05
L20	1	18 and 19	US-PGPUB	OR	ON	2007/03/08 14:05